

### MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY BREATH ALCOHOL PROGRAM

### CMI INTOXILYZER 5000 MAINTENANCE REPORT

Commission that we do not not not not not not not not not no	O MAINTENANCE	AEPON!		REPORT	
Complete this report at the time of the reg Complete this report whenever the instrur Retain the original and send a copy within	1 15 days to the Breath	maintenance check (r red and whenever it is Alcohol Program, DHS	ot to exceed 35 days). placed into service. S.		
66-005174 POPIAR	Bluff Police	PEPT	DATE OF INSPECTION 2/4//3	3	
330 N 2NO ST POPLAY	Kluff WAD	12001	TIME OF INSPECTION		
Uneuklist: Place a mark by each item i	found to be estletacion	corlo operation and the	0/55		
where determined.) Unmarked items must	be corrected before usi	ng instrument.	established limits. (Write	in observed values	
DVM TEST: (.350 ± .150) 408					
DIAGNOSTIC CHECK (PRINTOUT A	TTACHED)	DATE AND TIME	FROM PRINTOUT)	0157	
CHARACTER DISPLAY TEST					
PRINT TEST (PRINTOUT ATTACHED					
SIMULATOR SOLUTION SUPPLIER		. / U LOT # _	210100 EXP. D.	ATE 7/18/14	
SIMULATOR TEMPERATURE (34°C ±			SD 2748 EXP. D	ATE 1/10/14	
CALIBRATION CHECK - (ONLY ONE	STANDARD IS TO BE (	JSED PER MAINTEN	NCE REPORT)		
Hun three tests using a standard solution	n. All three tests must b	o within a government		have a spread of 005 or	
	orangara solution penny	useu. (PHINTOUT A	TACHED)	10 000, 10 paorde a ermi	
0.100% STANDARD - MUST READ	BETWEEN 0.095% AND	0.105% INCLUSIVE			
Q080% STANDARD - MUST READ Q000% STANDARD - MUST READ	BETWEEN 0.076% AND BETWEEN 0.038% AND	<del>20.084%_INCEUSIVE</del> 20.042%_INCLUSIVE			
TEST 1 # , U95					
1015	70	75	TEST 3 • , 09	25	
PERFORM RFI TEST (PRINTOUT ATTA	CHED)				
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)					
REFUSALS   004	.0509	.1014 /	.1519	Over .19 /	
LIST ANY NEW PARTS AND DESCRIBE ANY ALTERATION OR A USE OTHER SIDE IF NECESSARY).	IODIFICATION THAT WAS MADE T	O RESTORE THE INSTRUMENT	TO OPERATE SATISFACTORILY A	ND WITHIN ESTABLISHED LIMITS	
			•	ĺ	
				•	
NO NOW PARTS					
NSPECTING OFFICER					
GAT RANGE W. KMI # 55		PRINT PULL NAME	PRINTIPULL NAME  LUCHARD W. KNAMP		
PE II PERMIT NUMBER'EXPIRATION DATE  210210 7/7/13		TELEPHONE NUME	ER	.//	
		573 7	85 5776		
TURN COMPLETED REPORT TO THE: Breath Alcohol Program, Missouri Department of Health and Senior Services					
Southeast District Office 2875 James Blvd,					
	Poplar Bluff, MO 6390	)d		70	
580-1355 (2-08)	· Show arout uto 0000		•		



#### CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 12100 Alcohol Reference Solution for Simulator were analyzed by gas chromatography on July 20, 2012, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1217% (w/vol) ethyl alcohol. The expiration date for this lot number is July 18, 2014 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

> Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN122211-02 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.

330 H. ZND ST. POPLAR BLUFF MO INTOXILYZER - ALCOHOL ANALYZER MO MODEL 5000 SN 66-005174 02/04/2013 SN 66-005174 E235.23 INVALID TEST INHIBITED - RF1 02/04/2013 02:06 DIAGNOSTIC TEST 01:57 PROM CHECK E735.23
RAM CHECK
TEMP CHECK
PROCESSOR CHECK
SYNC PULSE
SYNC SPEED
NEG STABILITY
POS STABILITY
REF RANGE PASSED PASSED PASSED PASSED PASSED PASSED PASSED PASSED DIAGNOSTIC PASSED PRINTER CHECK ABCDEFGHIJKLMNOPORSTUVWXYZ 0123456789 SUBJECT'S NAME SUBJECT'S NAME TIME FIRST OBSERVED TIME FIRST OBSERVED INSTRUMENT LOCATION INSTRUMENT LOCATION **OPERATOR** OPERATOR nom MAMA ADDITIONAL INFORMATION AND JOH REMARKS ADDITIONAL INFORMATION AND / OR HEMARKS INTOXILYXER 6000 INSTRUMENT PAINTER CARD INTOXILYXER 5000 INSTRUMENT RRINTER CARD CMSU 1870-97 CMSU 1870-97

330 H. 2HD ST. POPLAR BLUFF MO INTOXILYZER - ALCOHOL ANALYZER NO MODEL 5000 SN 66-005174 02/04/2013 SN 66-005174 E735, 23 02/04/2013 01:58 ABCDEFGHIJKLMNOPORSTUUWXYZ0123456789
ABCDEFGHIJKLMNOPORSTUUWXYZ012345678910Habcde
ABCDEFGHIJKLMOPORSTUWXYZ012345678910Habcde
ABCDEFGHIJKLMNOPORSTUU
ABCDEFGHIJKLMNOPORSTUU
ABCDEFGHIJKLMNOPORSTUU TEST AIR BLANK CAL. CHECK AIR BLANK CAL. CHECK AIR BLANK CAL. CHECK AIR BLANK 02:01 02:02 02:02 .000 .095 . 000 . 095 .000 . 095 02:03 NO RFI PRESENT SUBJECT'S NAME SUBJECT'S NAME TIME FIRST OBSERVED INSTRUMENT LOCATION TÎME FIRST OBSERVED INSTRUMENT LOCATION

CMSU 1670-97

OPERATOR

namo

ADDITIONAL INFORMATION AND JOB REMARKS

GMSU 1670-97

INTOXILYXER 5000 INSTRUMENT PRINTER CARD

**OPERATOR** 

ADDITIONAL INFORMATION AND JOH REMARKS

INTOXILYXER 5000 INSTRUMENT PRINTER CARD

nim

# State of Missouri DEPARTMENT OF HEALTH



## PERMIT TYPE II



### RICHARD W KNAPP

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

INTOXILYZER 5000; ALCO-SENSOR IV W/PRINTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

air, issued under the provisions	or sections 577.020 through 577.041, R8Mo 1988.		
07/07/2011	Want		
Number 210210	Director of State Public Health Laboratory		
Expires 07/07/2013	Mayart T. Donnelly		
MO 580-0771 (7-86)	Director, Department of Health Leb. 4 (97-44		